





CPUMINI: Disassembly Instructions


CPUMINI Assembled

APPLIES TO: PAC-CPUMINI



CPUMINI: Disassembly Instructions

CPUMINI Components for breakdown



Material Identification

- A: Track
- Steel
- B: Hex Screw
- Steel
- C: Steel Washer (x3)
- Steel
- D: Small Plastic Washer (x2)
- Plastic
- E: Square Plate
- Steel
- F: Large Plastic Washer
- Plastic
- G: Flat Head Screw (x10)
- Steel
- H: Supporting Bracket
- Steel
- I: Handle
- Plastic
- J: Handle Screw
- Steel
- K: Nut (x4)
- Steel
- L: J Bracket 1
- Steel
- M: J Bracket 2
- Steel
- N: J Bracket 3
- Steel
- O: Knob
- Steel
- P: Sleeve
- Steel

Recommended Tools



Gloves



Goggles



1/2" Wrench



4mm Allen Wrench



Phillips-Head / Flathead Screwdriver

