






CPUCART-1: Disassembly Instructions

CPUCART-1 Assembled



CPUCART-1: Disassembly Instructions

CPUCART-1 Components for breakdown



Material Identification

A. Side Plates (x2)

- Steel 

B: Cushions (x3)

- EVA

C: Bottom Plate

- Steel 

D: Caster Sleeve (x4)

- Plastic

E: Caster with lock (x2)

- Nylon

F: Caster without lock (x2)

- Nylon

G: Knob (x4)

- Nylon

Recommended Tools



Gloves



Goggles