





WOW01: Disassembly Instructions

WOW01 Assembled



WOW01: Disassembly

WOW01 Components for breakdown



Material Identification

A: Platform

- Phenolic

B: Bracket & Wire Controller

- Steel 

C: Pneumatic Lift Pole

- Steel 

D: Five Star Base

- Steel 

E: Casters

- Plastic

Recommended Tools



Gloves



Goggles



Phillips Screwdriver